


**Health, Safety &
Wellbeing Department
SAFETY ALERT**



Ref: HSW/MASKS/2020/01

Issued: 20th July 2020

| | | |
|------|---------------------|-------------------------------------|
| FOR: | IMMEDIATE ACTION | <input checked="" type="checkbox"/> |
| | ACTION | <input type="checkbox"/> |
| | UPDATE | <input type="checkbox"/> |
| | INFORMATION REQUEST | <input type="checkbox"/> |

| SUBJECT: | FURTHER INFORMATION | |
|--|---|-----------|
| <p>There is one affected product:</p> <ul style="list-style-type: none"> - Mask, Type IIR - Supplier: Cardinal Health - NPC: BWM028 - MPC: AT74535UK <p>Therefore, a recall on all Cardinal Masks Type IIR Masks that for the above specification has been advised</p> |  | |
| PROBLEM: | | |
| The foam strip on the mask can flake and enter the wearer's airway or mouth; ties and/or stitching may detach from the mask. | | |
| ACTION BY: | | |
| Area Matron & Area Manager All Senior Sisters / Senior Charge Nurse & Donor Centre Managers | | |
| ACTION: | | |
| Identify, stop using and immediately dispose of all lots relating to BWM028 of the Cardinal Type IIR masks. See FURTHER INFORMATION for lot numbers | 0120GLP09 | 0516KLP09 |
| | 0302FLP09 | 0516MLP09 |
| | 0305HLP09 | 0517CLP10 |
| | 0310GLP09 | 0517JLP09 |
| | 0321FLP09 | 0518CLP10 |
| | 0321FLP09 | 0518LLP09 |
| | 0327FLP09 | 0518LLP09 |
| | 0402HLP09 | 0519ALP10 |
| | 0408HLP09 | 0519KLP09 |
| | 0411FLP09 | 0519MLP09 |
| | 0411HLP09 | 0520CLP10 |
| | 0413HLP09 | 0520JLP09 |
| | 0416HLP09 | 0520LLP09 |
| | 0419HLP09 | 0521KLP09 |

**Health, Safety &
Wellbeing Department
SAFETY ALERT**



| | | |
|--|-----------|-----------|
| | 0422HLP09 | 0521MLP09 |
| | 0425HLP09 | 0522ALP10 |
| | 0428HLP09 | 0522LLP09 |
| | 0431HLP09 | 0523CLP10 |
| | 0501ALP10 | 0523JLP09 |
| | 0502BLP10 | 0523MLP09 |
| | 0502CLP10 | 0524KLP09 |
| | 0502LLP09 | 0524LLP09 |
| | 0503DLP10 | 0525ALP10 |
| | 0503JLP09 | 0525JLP09 |
| | 0503KLP09 | 0526CLP10 |
| | 0504ALP10 | 0526LLP09 |
| | 0504LLP09 | 0526MLP09 |
| | 0505BLP10 | 0527KLP09 |
| | 0506ALP10 | 0528JLP09 |
| | 0506JLP09 | 0528LLP09 |
| | 0506KLP09 | 0529CLP10 |
| | 0506LLP09 | 0529KLP09 |
| | 0508DLP10 | 0529MLP09 |
| | 0508KLP09 | 0530JLP09 |
| | 0508MLP09 | 0531CLP10 |
| | 0509JLP09 | 0531KLP09 |
| | 0510KLP09 | |
| | 0511ALP10 | |
| | 0511JLP09 | |
| | 0511MLP09 | |
| | 0513ALP10 | |
| | 0513KLP09 | |
| | 0513MLP09 | |
| | 0514JLP09 | |
| | 0516ALP10 | |
| DISTRIBUTION: | | |
| All Blood Donation Teams and Donor Centre's | | |
| CONTACTS: | | |
| Becky Herrin, Health, Safety & Wellbeing Advisor | | |
| FEEDBACK REQUIREMENTS: | | |
| Confirm back advising if: (a) Masks were in use and have now been destroyed (b) Masks not in use | | |